

**From:** Phillip Hawes  
**Sent:** 30 October 2014 9:05 PM  
**To:** Regional Planning Interests Act  
**Cc:**  
**Subject:** Re: RPI14-002-UDMMeteor- New Figure for MDS RIDA

Dear Mitzi

Please find attached the information requested:

- Figure AC1 - Mine Infrastructure and PALU (I have labelled this AC1 so that it can be inserted into Appendix C which also has the tenure data)
- amended land use table (below)

Lot	Resource Activity	Total Area of Disturbance on Lot
4RP617701	Extraction activities – includes pit, dump, water and sediment management systems, haul roads, plant parking, temporary worker facilities, fire protection systems	259.04 ha
1SP164068	Mine support activities – includes mine infrastructure area, ROM, crushing and screening, stockpiles, loadout, water and sediment management systems, haul roads, sewerage treatment plant, fire protection systems	68.08 ha
1SP174071	Extraction activities - includes pit, dump, water and sediment management systems, haul roads, plant parking, temporary worker facilities, fire protection systems	50.72 ha
4SP170740	Mine support activities – includes haul roads, water and sediment management systems, security facilities and offices, quarry, fire protection systems	40.29 ha
2RP616045	Mine support activities – includes haul roads, water and sediment management systems, fire protection systems	8.52 ha

regards

**Phillip MH Hawes**  
Director  
[phillip@haringtonhawes.com](mailto:phillip@haringtonhawes.com)  
+61 (0) 412 611 519  
**Harington Hawes & Associates Pty Ltd**  
[www.haringtonhawes.com](http://www.haringtonhawes.com)